



## LAVATORY OR SINK

SHOWN WITH HOLDRITE #170-C COPPER BONDED BRACKET.  
SOLDER COPPER TUBING DIRECTLY TO THE BRACKET.

••••HUBBARD ENTERPRISES••••  
**HOLDRITE®**  
"Converting Makeshift Methods into Engineered Solutions"<sup>SM</sup>