


Cleanout Mode
with cleanout plug



DWV Test Mode
with TestRite® Wedge

TESTRITE®

CLEANOUT / TEST TEE & DWV TEST SYSTEM

Shown with the TestRite® Pipe Test System and Cleanout Tee for water or air testing of 2" through 6" DWV piping systems. Models available for use with ABS, PVC and No-Hub Cast Iron. (Shown installed in a No-Hub piping system)

THIS INFORMATION IS PROPRIETARY TO HOLDRITE AND IS SUBJECT TO CHANGE WITHOUT NOTICE. IT MAY NOT BE REPRODUCED IN PART OR WHOLE WITHOUT WRITTEN AUTHORIZATION.

HOLDRITE®
CONVERTING MAKESHIFT METHODS INTO ENGINEERED SOLUTIONSSM

800-321-0316 OR 760-744-6944 / FAX: 760-744-0507 / WWW.HOLDRITE.COM
50-005623-000, RevC