



LAVATORY OR SINK

SHOWN WITH HOLDRITE #170-C COPPER BONDED BRACKET.
SOLDER COPPER TUBING DIRECTLY TO THE BRACKET.

THIS INFORMATION IS PROPRIETARY TO HOLDRITE AND IS SUBJECT TO CHANGE WITHOUT NOTICE. IT MAY NOT BE REPRODUCED IN PART OR WHOLE WITHOUT WRITTEN AUTHORIZATION.

HOLDRITE[®]

CONVERTING MAKESHIFT METHODS INTO ENGINEERED SOLUTIONSSM

800-321-0316 OR 760-744-6944 / FAX: 760-744-0507 / WWW.HOLDRITE.COM / 50-005588-100, RevC (Lavatory or Sink with #170-C)