


**Cleanout Mode**  
with Cleanout Plug



**DWV Test Mode**  
with TESTRITE® Wedge

**TESTRITE®**

**CLEANOUT / TEST TEE & DWV TEST SYSTEM**

SHOWN WITH THE TESTRITE® PIPE TEST SYSTEM AND CLEANOUT TEE FOR WATER OR AIR TESTING OF 2" THROUGH 4" PIPING SYSTEMS. MODELS AVAILABLE FOR USE WITH ABS, PVC AND NO-HUB CAST IRON. (SHOWN INSTALLED IN ABS OR PVC PIPING SYSTEM)

.....HUBBARD ENTERPRISES.....  
**HOLDRITE®**  
"Converting Makeshift Methods into Engineered Solutions"™